




Design and performance of a 300 kV high voltage feedthrough for LAr TPCs

ETHZ





Simulations





High Voltage feedthrough test





LAr level at the nominal value

~20 min **Temperature** sensors

> LAr level at 10 cm above the nominal value

At this level, we observed bubbles coming from the HVFT. They were present even without any HV and without the HV cable connected. It is due to a heat input under investigation.

Heinzinger Power Supply Instabilities in the voltage at the end of We went down to 280 kV and we kept

Time

the scale of the PSU.

this value during half an hour.

High Voltage feedthrough test

"Long-term tests" letting different voltages during one hour

LAr level at 10 cm above the nominal value in all cases

At this level, we observed bubbles coming from the HVFT. They were present even without any HV and without the HV cable connected.

Voltage [kV]	Stability	Electric field at the critical point [kV/cm]
-275	Voltage stable but small current fluctuations between 0 and 2uA in the display of the PSU	56,5
-250	Voltage stable but small current fluctuations between 0 and 2uA in the display of the PSU	142
-100	Voltage stable	156

Conclusions

Preliminar test to confirm:

- •Stable operation of the HVFT in the 3x1x1 at -50 kV (eventually up to -100kV).
- •The HVFT was able to provide the maximum voltage given by the PSU inside LAr.
- •Heat input from the HVFT (under study) and small discharges due to the presence of bubbles (for a larger voltage such as -250 kV).